

2015-08-12A.jpg – Overall view of first trailer of contaminated material taken to Cody Landfill.

2015-08-12B.jpg – Closeup of some thick oil in trailer.

2015-08-12C.jpg – Another view of contaminated material in trailer.

2015-08-17A.jpg – Hardware embedded in contaminated material east of irrigation ditch.

2015-08-17B.jpg – Hardware embedded in contaminated material east of irrigation ditch.

2015-08-17C.jpg – Hardware embedded in contaminated material east of irrigation ditch.

2015-08-17D.jpg – Typical view of hard dry contaminated material in trench east of irrigation ditch.

2015-08-25A.jpg – Small surface (?) spill before removal, located approximately station 293 offset -081.

2015-08-25B.jpg – Small surface (?) spill before removal, located approximately station 293 offset -081.

2015-11-10A.jpg – Contaminated material in root wad of cottonwood tree. Tree is laying horizontal with top to right and view covers about four feet left-to-right. Contaminated material is about three feet thick here.

2015-11-10B.jpg – Contaminated material excavated from sloped-in pit east of cottonwood tree.

2015-11-10C.jpg – Root wad of cottonwood tree, showing contaminated material.

2015-11-10D.jpg – Root wad of cottonwood tree after picking off loose rocks and dirt with excavator.

2015-11-12A.jpg – Contaminated material in bottom of sloped-in pit. Shovel is 3.25 feet long.

2015-11-12B.jpg – Root wad of cottonwood tree after rolling about a quarter revolution to left. Shovel is 3.25 feet long.

2015-11-15A.jpg – Contaminated material around and under easternmost 6-inch steel pipe.