



ENGINEERING ASSOCIATES
A Wyoming Corporation
P.O. BOX 1900 ♦ 902 13TH STREET
CODY, WYOMING 82414
307-587-4911 ♦ FAX 587-2596

EAST SHERIDAN HILL
Glenn Borkenhagen
JOB NO. 19036

DATE: August 9, 2021

FIELD REPORT NO. 1

Owner: Glenn Borkenhagen	Contractor: Glenn Borkenhagen	
Substantial Completion: NA	Final Completion: NA	To Substantial
Major Items of Equipment on Job:		
Weather: See Below		

THE FOLLOWING WAS NOTED:

Tuesday, August 3, 2021 – Clear and 75° - CAS

Glenn and I visited McMillin pit to make sure the angle of repose for the rock at the pit would work with our design. We had designed a slope of 66.67% (1.5/1') and the rock at the pit would work. Attached are a couple of pictures from the existing site. Once Glenn worked the existing site, we changed the slope to 62.1% (1.61/1') since it fit the site better and was less of an angle than design.



SUBMITTED BY: Jim Flowers, CONSTRUCTION OBSERVER
COPIES TO: Glenn, CAS-PM, JOB No. 19036.00

Monday August 9, 2021 – Clear and 72° - JDF

I visited the site to photograph and inspect the excavation before the placement of the rock. Glenn was on site to provide specifics of the project.



SUBMITTED BY: Jim Flowers, CONSTRUCTION OBSERVER
COPIES TO: Glenn, CAS-PM, JOB No. 19036.00