



ENGINEERING ASSOCIATES
A Wyoming Corporation
P.O. BOX 1900 ♦ 902 13TH STREET
CODY, WYOMING 82414
307-587-4911 ♦ FAX 587-2596

EAST SHERIDAN HILL
Glenn Borkenhagen
JOB NO. 19036

DATE: September 1, 2021

FIELD REPORT NO. 2

Owner: Glenn Borkenhagen	Contractor: Glenn Borkenhagen	
Substantial Completion: NA	Final Completion: NA	To Substantial
Major Items of Equipment on Job:		
Weather: See Below		

THE FOLLOWING WAS NOTED:

Wednesday, September 1, 2021 – Clear and 70° - JDF

I visited the site to inspect the placement of the pit run material on the face of the slope and behind the slope. The material appeared dry but the slope was uniform. The excavation south of the slope was still about 4 feet to 4.5 feet deep.



SUBMITTED BY: Jim Flowers, CONSTRUCTION OBSERVER
COPIES TO: Glenn, CAS-PM, JOB No. 19036.00



Tuesday September 7, 2021 – Clear and 70° - JDF

Glenn was on site working on backfill at the crest of the slope. He was placing pit run material on the crest and was preparing to compact the crest and then backfill the backslope to the 2 percent grade to the south.



SUBMITTED BY: Jim Flowers, CONSTRUCTION OBSERVER
COPIES TO: Glenn, CAS-PM, JOB No. 19036.00



SUBMITTED BY: Jim Flowers, CONSTRUCTION OBSERVER
COPIES TO: Glenn, CAS-PM, JOB No. 19036.00