



ENGINEERING ASSOCIATES
A Wyoming Corporation
P.O. BOX 1900 ♦ 902 13TH STREET
CODY, WYOMING 82414
307-587-4911 ♦ FAX 587-2596

EAST SHERIDAN HILL
Glenn Borkenhagen
JOB NO. 19036

September 14,
DATE: 2021

FIELD REPORT NO. 3

Owner: Glenn Borkenhagen	Contractor: Glenn Borkenhagen	
Substantial Completion: NA	Final Completion: NA	To Substantial
Major Items of Equipment on Job:		
Weather: See Below		


THE FOLLOWING WAS NOTED:

Tuesday, September 14 2021 – Clear and 70° - JDF

I visited the site to inspect the final material placement. The backslope was filled in at approximately 2% slope to the south. For all purposes he is finished for now with the slope stabilization work. Glenn had placed topsoil up to the crest for seeding that will be done at a later date.



SUBMITTED BY: Jim Flowers, CONSTRUCTION OBSERVER
COPIES TO: Glenn, CAS-PM, JOB No. 19036.00



SUBMITTED BY: Jim Flowers, CONSTRUCTION OBSERVER
COPIES TO: Glenn, CAS-PM, JOB No. 19036.00